From: "Wallingford, Jonni B." <wallingfordjb@cdmsmith.com>

To: "Sheldrake, Sean" < sheldrake.sean@epa.gov>

"Zhen, Davis" <Zhen.Davis@epa.gov>

CC: younghs@cdmsmith.com

"Scott Coffey" <coffeyse@cdmsmith.com>

"Vickstrom, Kyle E." <vickstromke@cdmsmith.com>

Date: 8/28/2018 1:09:45 PM Subject: Surface Sediment Sampling

Attachments: IMG 20180828 130646253 HDR.jpg

IMG 20180828 124908032.jpg IMG 20180828 122827383 HDR.jpg

Good afternoon,

The Cayuse is currently sampling B479 (RM 26), attempt #4 - Alt location area 52. The crew probed the area in 6 different locations and all material consisted of very hard sand with cobbles.

A previous sample was collected at B480 that had very little fines (approximately 15ft away from current sampling location). The Pre-RD group is discussing the idea of abandoning the sample site B479 and moving on to B478, as the target site is comprised of shallow hard sand, and rip rap with cobbles.

Jonni

Photo 1: taget location B479

Photo 2: location (close up)

Photo 3: Pre-RD sampling attempt #4

Get Outlook for Androidhttps://aka.ms/ghei36